GMS ARCHITECTS 1150 Paredes Line Rd. Brownsville TX 78526 (956) 546-0110 fax (956) 546-0196

IDEA PUBLIC SCHOOLS ENVELOPE IMPROVEMENTS IDEA DONNA

PROJECT # 33-DBE-0424

IDEA Public Schools Board of Directors 2024

Rio Grande Valley Regional Board 2024

Collin Sewell	Chair	Maria Antonia Chapa	Member
Ed Rivera	Vice Chair	Cerise R. de Garduno	Member
Erich Holmsten	Treasurer	Sarah Garza	Member
Ryan Vaughan	Secretary	Zulieda Lopez-Habbouche	Member
Michael Adams	Member	Andrea Rodriguez	Member
Gary Lindgren	Member	Alyssa L. Romero	Member
Theresa Barrera-Shaw	Member	Bobby Saenz	Member
Nanette Cocero	Member	CJ Sanchez	Member
		Jesus Zepeda	Member

DRAWING INDEX

IDEA DONNA

A1.01 CAMPUS SITE PLAN
A1.02 PARTIAL SITE PLAN; SIDEWALK DETAILS
A2.01 ROOF PLANS

2.02 ROOF DETAILS 3.01 ELEVATIONS - BLDG. A 3.02 PARTIAL ELEVATIONS - BLDG A


A4.02 DETAILS A4.03 DETAILS


ARCHITECTS


GOMEZ MENDEZ SAENZ, INC.


1150 PAREDES LINE RD. BROWNSVILLE, TX. 78521 PH. (956) 546-0110 FAX. (956) 546-0196











© Copyright 2024 Gomez Mendez Saenz Inc.


Architects-Planners Interior Designers

Roan Gomez, AIA

IDEA DONNA

No. REVISIONS BY





GENERAL ROOFING NOTES:

WHERE APPLICABLE, THE RE-ROOFING PORTION OF THIS PROJECT HAS BEEN DESIGNED TO BE IN COMPLIANCE WITH ALL APPLICABLE CODES, INCLUDING BUT NOT LIMITED TO THE INTERNATIONAL BUILDING CODE (LATEST EDITION). THE SPECIFIED ROOFING SYSTEM MEETS FACTORY MUTUAL RESEARCH CORPORATION STANDARD 4470 APPROVAL REQUIREMENTS FOR CLASS 1 FIRE AND 1-90 WINDSTORM CLASSIFICATION AND CLASS 1-SH HAIL RATING.

AT ALL NEW ROOF WORK AREAS AND PRIOR TO CONSTRUCTION, WALK THROUGH EVERY ROOM IN BUILDINGS WITH OWNER'S REPRESENTATIVE AND IDENTIFY WATER DAMAGED CEILINGS, WALLS, ETC. TO DETERMINE LOCATION & AMOUNTS OF INTERIOR WATER DAMAGE. PROVIDE COPY OF THIS LIST TO ARCHITECT.

 $\hbox{IT IS THE CONTRACTOR'S RESPONSIBILITY TO FIELD-VERIFY EXISTING CONDITIONS, DIMENSIONS, QUANTITIES, AND ETC., PRIOR TO BIDDING. } \\$

INSPECT ALL DECK AREAS FOR DAMAGE AND REPORT TO ARCHITECT ANY DEFICIENCIES FOUND.

REPLACE ALL LEAD ROOF JACKS VENTS WITH NEW LEADS.

INSTALL NEW DOUBLE-WALL HEATER VENTS AND EXTEND FLUES TO MATCH EXISTING AS REQUIRED TO ACCOMMODATE NEW ROOF THICKNESS AND TO PROVIDE A MINIMUM 12-INCH HEIGHT FROM THE NEW ROOF SURFACE TO THE BOTTOM OF THE VENT CAP.

EXTEND ALL DUCTS, PIPES, CONDUIT, WIRE AND ETC., AS REQUIRED TO ACCOMMODATE NEW ROOF SYSTEM.

PROVIDE POSITIVE DRAINAGE, BY USE OF CRICKETS, IN AND AROUND ALL ROOF TOP EQUIPMENT TO AREA ROOF DRAINS.

AT ALL EXISTING UTILITY PIPING, CONDUIT, ETC. PROVIDE PROPER SIZED PIPE STANDS AS SPECIFIED, UNDER ALL PIPES AND CONDUIT, AT 8'-0" O.C. UNLESS A NARROWER SPACING IS REQUIRED FOR PROPER SUPPORT.

THE CONTRACTOR SHALL BE RESPONSIBLE FOR HAVING A LICENSED ELECTRICAL, PLUMBING AND MECHANICAL CONTRACTOR CAREFULLY REMOVE, RAISE OR MODIFY AND CAREFULLY REINSTALL EXISTING OPERATING MECHANICAL, ELECTRICAL, PLUMBING AND RELATED EQUIPMENT AS REQUIRED TO COMPLETE THE WORK.

THE CONTRACTOR SHALL TAKE EXTREME CARE IN WORKING WITH EXISTING ITEMS THAT ARE TO REMAIN. DAMAGE CAUSED BY THE CONSTRUCTION PROCESS WILL BE REPAIRED BY THE CONTRACTOR AT NO COST TO THE OWNER.

AT THE COMPLETION OF ALL ROOFING WORK AT EACH BUILDING, ALL EXISTING ROOF DRAINS AND RELATED PIPING SHALL BE WATER TESTED, CHECKED AND CERTIFIED BY A LICENSED PLUMING CONTRACTOR TO BE OPERATIONAL AND LEAK FREE.

KEYED NOTES

- 01 PROVIDE NEW FLASHING/SEALANT AROUND ROOF HATCH
- PROVIDE NEW FLASHING/SEALANT AROUND ROOF PENETRATION (TYP.)
 REFER TO SHEET A2.02
- 03 REINSTALL CONDENSATE LINES (TYP.)

 04 PROVIDE NEW FLASHING/SEALANT AROUND VENTS/EXHAUST (TYP.)
- 05 PROVIDE NEW FLASHING/SEALANT AROUND ROOF DRAIN (TYP.)
- PROVIDE NEW CURBS AND FLASHING/SEALANT AROUND EXISTING MECHANICAL EQUIPMENT. (TYP.)
- NEW BITUMEN ROOF OVER NEW RECOVERY BOARD OVER NEW TAPERED RIGID INSULATION.

ROOF: SCOPE OF WORK

REMOVE ROOFING MEMBRANE TO RECOVER BOARD.

2. REPLACE INSULATION AS REQUIRED TO PROVIDE POSITIVE SLOPE TO ROOF DRAINS

08 PROVIDE NEW CANT STRIPS AT ALL PARAPET WALLS (TYP.)

PROVIDE NEW PARAPET CAP FLASHING (TYP.)

10 LOW SPOT IN ROOF INSULATION

REPAIR LOW AREA WHERE PONDING OCCURS.
 INSTALL NEW CANT AND PARAPET FLASHING.

5. INSTALL NEW MODIFIED BITUMEN ROOFING SYSTEM.6. REFER TO SHEET A2.02 FOR DETAILS

PURGE DRAIN LINES FROM ROOF LEVEL TO DISCHARGE POINTS.
 PERFORM WATER TEST AT ALL ROOF DRAINS.

REPAIR DRAIN LINES AND RE-SEAT ROOF DRAINS.
 REPAIR ELECTRICAL AND MECHANICAL ROOF PENETRATIONS

11. INSTALL NEW CAP FASCIA AND ACCESSORIES.

INSTALL WALKWAY SYSTEM AT ALL ROOFTOP EQUIPMENT.PROVIDE CONCRETE SPLASH BLOCK AT EXTERIOR DOWNSPOUTS.

Apr 04, 2024 — 10:56amC:\Users\rgg\AppData\Local\Temp\AcPublish_29524\A5.00.dwg



BUIL

© Copyright 2024 Gomez Mendez Saenz Ind Architects-Planners


Interior Designers Roan Gomez, Al IDEA DONNA

Apr 04, 2024 - 10:56amC:\Users\rgg\AppData\Local\Temp\AcPublish_29524\A5.00.dwg











01 NORTH ELEVATION
SCALE: 1/8" = 1'-0"

02 SOUTH ELEVATION
SCALE: 1/8" = 1'-0"



WEST ELEVATION



04 EAST ELEVATION

SCALE: 1/8" = 1'-0"

KEYED NOTES

- 01 PAINT PLASTER, TYP.
- REPLACE HORIZONTAL AND/OR VERTICAL, OR CORNER PLASTER BEADS. REFER TO DETAILS FROM SHEET A4.01
- 03 REPLACE ALL SEALANT & BACKER RODS @ DOORS/WINDOWS/CONTROL JOINTS, TYP.
- 04 REMOVE AND REPLACE LOOSE OR DAMAGED BRICK VENEER/METAL LATHE AND CORRECT WATER PROOFING MEMBRANE AS PER DETAILS FROM SHEETA4.01
- 05 ADD SPLASH BLOCKS, TYP.
- 06 RE-SEAL ALL WALL EXTERIOR PENETRATIONS, TYP.
- 07 REMOVE RUST AND COLD GALVANIZE ROOF FRAMING/EXPOSED METAL
- 08 REPLACE GUTTER/DOWNSPOUT/BOOT
- CLUSTER OF HAIRLINE CRACKS. WHEN CRACK IS 1/2" OR MORE, REPAIR WITH BACKER ROD AND CAULKING BEFORE PAINTING
- PATCH AND REPAIR PLASTER TO MATCH EXISTING FINISH.
 REFER TO DETAILS:A4.01
- 11 CLEAN AND SEAL INSIDE CORNER
- CORRECT DRIP FLASHING ABOVE HEADER AT METAL PANEL, ADD 12 BREAK METAL HEADER FLASHING WITH 4" DRIP. REFER TO DETAILS
- 13 RE-SEAL AROUND COVE LIGHT, PENETRATION, TYP.
- REPLACE PLASTER BEADS AND/OR PLASTER ON INSIDE CORNER OR UNDERSIDE
- CORRECT FLASHING AT WINDOW SILL AT METAL PANEL, REFER TO DETAILS 05-06/A4.02
- 16 CORRECT FLASHING AT WINDOW SILL AT BRICK, REFER TO DETAILS 05-08/A4.03
- REMOVE WINDOW AND REPAIR FLASHING ON ALL SIDES. REINSTALL WINDOW, REFER TO DETAIL SHEETS A4.00 SERIES ADD BREAK METAL HEADER FLASHING WITH $\frac{1}{4}$ " DRIP, REPAIR WINDOW FLASHING, AND ADD BREAK METAL SILL FLASHING AND SILL PAN. REFER TO
- 19 REPLACE FLASHING AT TRANSITION FROM CANOPY TO BUILIDING
- 20 WATER TESTED AREA WITH HISTORY OF LEAKS
- 21 REPLACE METAL PANELS

BUILDING A: SCOPE OF WORK


- POWER WASH EXTERIOR STUCCO AND MASONRY VENEER.
- WATER TEST EXTERIOR WINDOWS AND STOREFRONTS. REMOVE AND REPLACE BACKER ROD AND SEALANT AT ALL EXTERIOR DOOR AND WINDOW ASSEMBLIES.
- REMOVE AND REPLACE BACKER ROD AND SEALANT AT ALL MASONRY CONTROL JOINTS.
- REPAIR STUCCO CONTROL JOINTS AND SILL TRIM PIECES. REPAIR EXTERIOR METAL WALL PANELS AND TRIM.
- REMOVE EXCESS TOPSOIL WHERE IT CONTACTS METAL PANELS. INSTALL BREAK METAL SILL TRIM AT MASONRY VENEER.
- REPAIR FLASHING AT AIRSPACE AT MASONRY.
- 10. APPLY ELASTOMERIC COATING OVER STUCCO VENEER FOR THE ENTIRE BUILDING.
- PAINT ALL EXTERIOR SURFACES TO MATCH EXISTING SECURE ALL DISLODGED METAL PANELS. 12. REPLACE EXISTING EXTERIOR WATERPROOFING/SEALANT JOINTS.
- REPLACE FLASHING OVER BRICK WAINSCOT, AND PROVIDE POSITIVE DRAINAGE 1/4" PER 1'-0". 14. REPLACE SILL FLASHING AT BUILDING BASE WHERE DAMAGED, AND RE-GRADE IN AREAS OF PONDING
- SO THAT AT LEAST 6" ARE CLEAR FROM GRADE TO SILL FLASHING. 15. RE-APPLY WINDOW FLASHING ON ALL SIDES OF WINDOW PATCH AND REPAIR ALL AFFECTED SURFACES TO MATCH


SCALE: 1/4" = 1'-0"


SCOPE OF WORK:


- 1. Remove sealant at all exterior doors, windows and masonry control 2. Install backer rod and sealant at windows, doors and masonry
- control joints. 3. Install door threshold at exterior doors.
- 4. Remove fixtures and Seal all wall penetrations at electrical and
- plumbing fixtures.
 5. 5. Refer to Sheet A6.01 for window / door elevations


















04 PARTIAL ELEVATION
SCALE: 1/4" = 1'-0"

01 PARTIAL ELEVATION
SCALE: 1/4" = 1'-0"










08 PARTIAL ELEVATION
SCALE: 1/4" = 1'-0"



UBLIC SCHOO"A" ENVELOPE AND


I D E A P I BUILDING

o. | REVISIONS | BY

TYPICAL VERTICAL
(HORIZONTAL SIM.)

CONTROL JOINT @ PLASTER


SCALE: 6" = 1'-0"



TYPICAL CORNER DETAIL

02 PLASTER

SCALE: 6" = 1'-0"




PLASTER REPAIR DETAIL

(TOP PORTION REMOVED)

O3

SCALE: 6" = 1'-0"




PLASTER REPAIR DETAIL

(BOTTOM PORTION REMOVED)

O4


SCALE: 6" = 1'-0"



EXPANSION JOINT @


O5 STUCCO

SCALE: 6" = 1'-0"



TYPICAL DRIP DETAIL @ PLASTER


O6 SCALE: 6" = 1'-0"




TYPICAL VERTICAL

OT CONTROL JOINT @ BRICK


SCALE: 6" = 1'-0"



7B METAL PANEL TRIM @ BRICK (JAMB VIEW)




TYPICAL DEMOLITION
08 DETAIL @ WAINSCOT




TYPICAL STUCCO REPAIR @ WAINSCOT - STUD WALL

O9 SCALE: 6" = 1'-0"




TYPICAL DEMOLITION

10 DETAIL @ WAINSCOT



TYPICAL STUCCO REPAIR @ 11 WAINSCOT - CMU WALL



© Copyright 2024
Gomez Mendez Saenz Inc.
Architects-Planners
Interior Designers

Date:
02/04/2024
Scale:
As Noted
Project Architect:
Roan Gomez, AIA
Drawn By:
CG,RG
Job No.
IDEA DONNA
Sheet:

Gomez Mendez Saenz Ind Architects-Planners


Roan Gomez, AIA,


A4.02


IDEA DONNA

GMS ARCHITECT

1150 Paredes Line Rd Brownsville TX 78526 (956) 546-0110 fax (956) 546-0196







TYPICAL DEMOLITION

O1

SCALE: 6" = 1'-0"


TYPICAL METAL PANEL
REPAIR @ WINDOW HEADER


02
SCALE: 6" = 1'-0"


TYPICAL DEMOLITION
DETAIL @ METAL PANEL WINDOW


13
| SCALE: 6" = 1'-0"

TYPICAL METAL PANEL
REPAIR @ WINDOW JAMB
04
SCALE: 6" = 1'-0"









TYPICAL DEMOLITION

DETAIL @ METAL PANEL SILL

05

SCALE: 6" = 1'-0"

TYPICAL METAL PANEL REPAIR @ WINDOW SILL SCALE: 6" = 1'-0"

TYPICAL DEMOLITION

OTHER DETAIL @ STUCCO SILL

SCALE: 6" = 1'-0"

TYPICAL STUCCO REPAIR @ STUCCO SILL

O8
SCALE: 6" = 1'-0"

I D E A P U B L I C S C H O O L S

BUILDING "A" ENVELOPE AND ROOF REPAIRS

DONNA, TEXAS

© Copyright 2024 Gomez Mendez Saenz Ind Architects-Planners

IDEA DONNA

A4.03

o. REVISIONS BY

GMS ARCHITECT

1150 Paredes Line Rd

Brownsville TX 78526

(956) 546-0110

fax (956) 546-0196